


Pioneer

Service Manual



BDP-LX55

ORDER NO.
RRV4285

Blu-ray 3D™ PLAYER

BDP-LX55

BDP-53FD

THIS MANUAL IS APPLICABLE TO THE FOLLOWING MODEL(S) AND TYPE(S).

Model	Type	Power Requirement	DVD Region No.	BD Region No.	Serial No.	Remarks
BDP-LX55	YXCN5	AC 100 V to 240 V	2	B	&&&&#####YY	YY:Europe
BDP-LX55	VXCN5	AC 100 V to 240 V	2	B	&&&&#####GB	GB:U.K
BDP-LX55	FWLXCN	AC 100 V to 240 V	3	A	&&&&#####TA	TA:Taiwan
BDP-53FD	UCXCN	AC 120 V	1	A	&&&&#####UC	UC:NORTH AMERICA



PIONEER CORPORATION 1-1, Shin-ogura, Saiwai-ku, Kawasaki-shi, Kanagawa 212-0031, Japan
PIONEER ELECTRONICS (USA) INC. P.O. Box 1760, Long Beach, CA 90801-1760, U.S.A.
PIONEER EUROPE NV Haven 1087, Keetberglaan 1, 9120 Melsele, Belgium
PIONEER ELECTRONICS ASIACENTRE PTE. LTD. 253 Alexandra Road, #04-01, Singapore 159936
©PIONEER CORPORATION 2012

K-FZV MAR. 2012 Printed in Japan

MODEL No.	* SER. No	S/M No.	PG
Refer to following pages.			
DETAIL			
SYMPTOM	Can't open the disc tray.		
CAUSE	Due to loading rubber belt deteriorated.		
SERVICE REMEDY	Replace the loading rubber belt.		
FACTORY COUNTER-MEASURE	None		

SYMPTOM

Although the **loading motor sound is heard** after pressing OPEN/CLOSE button, the **disc tray does not open** due to the loading belt slipping.
For the above symptom, the loading rubber belt has been available.



+	CURRENT PARTS		CO DE	NEW PARTS	
	SYMBOL/DESCRIPTION	PART NUMBER		PART NUMBER	SYMBOL/DESCRIPTION
A			✓	59-968030-000-TL	BELT
B				59-108150-000-TL	BELT

(!): You should use specified parts by safety regulations.

PIONEER SERVICE NETWORK CORPORATION

NOTE: PARTS CODE

H. KISHIDA, MANAGER
HE Technical Support Group
Technical Support Division

1: Changeable from old to new. Memo: QA68-N005-A
2: Not Interchangeable at all. TB-45325
3: Interchangeable in both ways.
5: Do not use old parts.

(E1 W1)